

60X 85 American Pluverizer serial number 8396 Shredder installed 2001 evaluation report

Location:

Rifkin Scrap Iron and Metal 1445 North Niagara Street Saginaw, MI 48602 Office 1-989-752-7646

Prepared by:

Wendt Corporation
Jim Armstrong
Rotor and casting specialist
Office 1-716-391-1223
Cell 1-716-622-1393
Date of evaluation: 9-2-15





Table of contents:

Page 3-7 Infeed conveyor

Page 8-10 Feed Chute

Page 11-14 Feed Rolls and Frame

Page 15-22 Shredder Mill Cage

Page 23-29 Rotor & Drive Shaft

Page 30-33 Casting Mill Liners

Page 34-38 Under mill feeder

Page 39-42 Hydraulic power units

Page 43-58 Electrical

Page 59-68 Spare Parts

Page 69 Decibel Sound Readings (db) documentation

Page 71 Evaluation Summary

Attachments: Main Motor inspection and service reports 2013 &2014



Infeed Conveyor



Main Structural Support in good condition. No major material trapped on belt







Hydraulic motor drive pulley clean and free of hydraulic leaks head shaft in good condition



Transition from Infeed Conveyor to chute excellent condition. Side walls great condition.






Structural frame work in good shape under the main frame



All steel flights in good condition with a few with minor bends









Load section and tail pulley in good condition clear from debris and tail pillow blocks covered with shield





Tail shaft pulley and tail shaft pillow block bearing in good condition



Feed Chute



Main floor and side walls in excellent condition with new installed wear strips



Plug welded floor liners seen under bottom of feed chute





Outside walls of chute in excellent shape and straight



Bottom of chute fabrication in good solid welded condition





Bottom of feed chute full view



Feed Roll Drums and Frame





Lower feed roll drum couple teeth missing should be replace. Drum in good condition





No wire wrap around end of feed roll drum shafts with no evidence of the shafts being gouged from a cutting torch



Feed roll frame in good condition straight with no evident weld cracking or twisting





Feed roll drum chain drive, sprockets and chain in great condition. No hydraulic leaks from drive motor or feed roll hydraulic lift cylinder(Photo rotated 90 degrees)



End of the feed roll frame boxed section all welds intact with no cracking





Feed roll frame rectangular cross member torque tube in great shape more robust fabrication added by customer



Mid-section and base weldment



Mid-section hydraulic lift cylinder in excellent condition. No leaks and pivot pins in great condition.

Bent side wall needs repaired







All welds on mid-section pivot arms in good condition



Base box walls in good condition






Base weld gussets no cracks evident in excellent condition





















Reject door fabrications and reject door casting pivot attachment in excellent condition . No hydraulic leaks in cylinder



Bonnet or deflector top tight to the mid-section





Bearing pedestals in good condition with no evidence of weld repair to the base





The shredder box springs appear in great condition and functional





Rotor and Drive Shaft





Rotor in good condition 280,00 input tons. Tight to main rotor shaft. Tie rods look like there has been a repair.





End discs caps need to be replaced extreme wash from the material impacting the end disc face. Side chute entrance liners should be replace and for additional protection.



Small amount of wash on mill base side walls should be weld repaired. New wipers on rotor disc have been added that will help this condition.





Welded round stock has been added for protecting the cap from hammer wash.

They will not last for any length of time as the caps should be replaced







Weld repair has been added to the spider arm. This tells me the rotor stack is not tight and will only keep the rotor together for a shorter period of time.



Bearing temperature probes in good condition both side. Minimal oil leaks from bearings.





Bearing shim plate have been welded to shredder pedestals bearing stop blocks are welded permanent. This could be additional work if the bearing needs replaced or a broken rotor tie rod needs replace.



Rotor universal drive shaft



Safety cover excellent condition



Motor coupling end with guard excellent condition





Rotor coupling to drive shaft in excellent condition



Mill Liners



Casting anvil bolts from back side of Mill base under chute are all tight and have not moved All surface welds appear in good condition on anvil seat.





Base section side liner bolts are tight and show no movement







Double beam 4.25" x 8" openings staggered appear to be in good condition ½ life



Reject door front wall liners and side wall liners appear in good condition.

Minimal wash on side wall track facing rotor end discs.





Upper mid-section liner bolts in good condition with no movement observed.

Holes in mid-section walls for liners in great condition.

Front wall tie rods in excellent condition with weld repair to the box side walls and the installation of steel bushings.



Under mill Feeder



Exit trough pan has rust thru occurring



Actuating arms in good condition





No visual welding issues to main frame













Pulley belt missing that drives the eccentric





Conciderable rust on eccentric drive shaft. Cover should be removed and greased



Fisher steel plate should be added to the bottom of the exit chute



Hydraulic Power Units

Bearing Lube Unit - 2hp motor Infeed conveyor 30 hp motor Feed roll drums 60 hp motor with 5 hp recirculating pump Maintenance 15 hp and reject door 50 hp



Bearing lube unit



















Feed roll drums and recirculating pump
All hydraulic tanks in great condition free of hydraulic leeks and new filters installed
All oil under pumps dry and clean



Electrical





















Lose wiring needs to be reinstalled back into wire ways











Motor Liquid Rheostat in good mechanical condition





Main Shredder motor Alstom 2500 hp 592 Rpm Slip Ring motor 4160 volt









Motor Arcing detection



Main Motor control



	LIMITAMP® CONTROL COMMANDE LIMITAMP®	
100	MODELCR194A118A2 CAT. 0871X0193Q01A01 MODELE DIAGRAM 33987624 Sh. 3	
	SCHÉMA POWER FUSE CAT. NO.	
	3 PHASE 60 HZ 4190 VOLTS AC 60 KV BIL VOLTS C.A. KV TTC CONT. CUR. RATING 365 RMS AMPERES 40°C AMB. COUR., SERVICE CONT. EFF., A, 40°C AMBIANTE SERVICE LIMIT CUR. RATING RMS AMPERES COURANT LIMITE EN SERVICE HORIZ, BUS CUR. RATING 1200 RMS AMPERES COUR. NOM., BUS HORIZON EFF., AMPERES CONTROL CIRCUIT 116 VOLTS CIRC. DE COMMANDE POWER CIRCUIT MAX. VOLTS 4.6K AC	
	CIRCUIT DE PUISSANCE, MAX. LOAD: TYPE IND 2600HP , FULL LOAD CUR. 366 AMP CHARGE: TYPE COUR. PLEINE CH. W.R. MOTOR SEC. WOTOR SEC. WOTEUR SECOND., ROTOR BOB. SYNC. FIELD V CA. AR P.F. CHAMP SYNC. V CC A F.P.	
	CAUTION BEFORE INSTALLING OR OPERATING READ INSTRUCTIONS. ATTENTION. URE LES INSTRUCTIONS AVANT DE PROCÉDER À L'INSTALLATION. GEH-6305 DEF-002 GEH-6306 GEF-8016	00 100 1001
	DO NOT OPERATE STARTERS FURNISHED WITH CURRENT TRANSFORMERS UNLESS RELAY ELEMENTS ARE INSTALLED. NE PAS UTILISER LES DÉMARRIEURS FOURNIS AVEC LES TRANSFORMATEURS DE COURANT AVANT QUE LES RELAIS SOIENT INSTALLES.	09/02/2015
	55B533231P1 MEBANE, N.C. MADE IN USA	

Main motor control Tag



Main control operator's screens

























Operators Chair hand controls





Spare Parts



New Spider Rotor







Drum Magnet skin cover









New Rotor bearings





(2) Universal drive shaft for the 2500 hp motor and (1) for the 1500 hp motor not shown



Spare rebuild Mid-section tilt cylinders



New Reject door cylinder



Spare conveyor bearings



Casting liner bolts





Roller wheels and Links for infeed chain



Spare rotor shaft coupling for the 1500 hp motor drive shaft



Anvil Bolts



Cylinder pivot yokes






Pivot Pins for Mid section





Bearing shim plates (replacements new)







Evaluation Summary

Considering the shredder was installed in 2001 it is very evident after review the shredder and this report there has been good maintenance performed on this piece of equipment.

The customer has a lot of time and money invested in the proper maintenance and care of this shredder over the 14 year life span.

There are the majority of the important major spare parts that are in inventory to minimize down time.

Documentation was supplied to me for my review on the Hydraulic power units, Electrical controls and motor maintenance records on file.

There were only a few issues that would need to be taken care of.

Example the mid-section wall bent will need to heated and pulled back into position.

Welding of the base were the rotor end disc is causing wear to the side walls.

Pulley belt replacement on the under mill feeder.

This shredder is in ready to run condition.

Customer does not have any additional castings in his inventory and should be considered for purchase.

Example: Side liners, Anvil, Solid Grates, Open Grates, Front wall, Back wall grates, Hammer pin shafts and Hammers