



Work Orders List for 02/03/2024 - 03/31/2025







WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
#611 BALER06 - 500 HOUR EQUIPMENT INSPECTION Type: Reactive Medium PREVENTIVE T PARTS TEAM SAMANTHA FORRINGER	EVERETT BALER06 SIERRA	✓ Done Completed by SAMANTHA FORRINGER on 02/14/2024		Lock Out Equipment: ✓ N/A Unlock Equipment: ✓ N/A
#691 Blades flip Type: Reactive Medium DJ HEGARTY	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 02/26/2024	Total Time 5h 35m 19s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST		PROCEDURE ANSWERS
#729 BALER06 - Seirra Hydraulic breather filter Type: Reactive MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 03/01/2024	Total Part Costs Total Time Total Costs	\$310.66 1h 6m 27s \$310.66	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#776 BALER06 Sierra De-Rate faults Type: Reactive Medium MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 03/06/2024	Total Time	3h 49m 34s	Take a picture when you Lock Out the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
				Take a picture when you Unlock the equipment : 
#772 BALER06 Codes on sierra 06 Type: Reactive High DJ HEGARTY	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 03/07/2024		Take a picture when you Lock Out the equipment : 
				Take a picture when you Unlock the equipment : 
#795 baler06 Sierra Return filters Type: Reactive Medium SAMANTHA FORRINGER DAN NASSAR MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by SAMANTHA FORRINGER on 03/08/2024	Total Part Costs \$2,067.83 Total Time 5h 48m 57s Total Costs \$2,067.83	Take a picture when you Lock Out the equipment : 


WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
				Take a picture when you Unlock the equipment :
				
#786 BALER06 - REPLACE HYDRAULIC FILTERS - PM Type: Preventive T PREVENTATIVE MAINTANCE DJ HEGARTY	EVERETT BALER06 SIERRA	03/06/2024 ✓ Done Completed by DJ HEGARTY on 03/11/2024	Total Part Costs \$1,169.94 Total Time 0m 14s Total Costs \$1,169.94	Take a picture when you Lock Out the equipment : 
				Take a picture when you Unlock the equipment :
				

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
#805 BALER06 - REPLACE HYDRAULIC OIL - PM Type: Reactive  PREVENTATIVE MAINTANCE DJ HEGARTY	EVERETT BALER06 SIERRA	03/08/2024  Done Completed by DJ HEGARTY on 03/11/2024	Total Time 5h 13m 53s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#1076 BALER 06 Sierra codes Type: Reactive  High DJ HEGARTY	EVERETT BALER06 SIERRA	 Done Completed by DJ HEGARTY on 04/04/2024	Total Time 1h 41m 50s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
#1077 BALER 06 IN Derate Type: Reactive High DAN NASSAR	EVERETT BALER06 SIERRA	✓ Done Completed by DAN NASSAR on 04/04/2024	Total Time 8h 27m 8s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#1013 BALER06 HOURMETER Type: Reactive High DJ HEGARTY	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 04/10/2024	Total Part Costs \$1,710.23 Total Costs \$1,710.23	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST		PROCEDURE ANSWERS
#1387 Blow out/fluid check Type: Reactive Low MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 05/03/2024	Total Time	18m 36s	Take a picture when you Lock Out the equipment : 
					Take a picture when you Unlock the equipment : 
#1274 Bailer06 hose Type: Reactive High SAMANTHA FORRINGER DJ HEGARTY	EVERETT BALER06 SIERRA	✓ Done Completed by SAMANTHA FORRINGER on 05/23/2024	Total Part Costs Total Time Total Costs	\$2,685.76 2h 28m 14s \$2,685.76	Take a picture when you Lock Out the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
				Take a picture when you Unlock the equipment : 
#1434 Sierra 06 Type: Reactive High SAMANTHA FORRINGER MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by SAMANTHA FORRINGER on 05/23/2024	Total Part Costs \$2,685.76 Total Time 1h 46m 36s Total Costs \$2,685.76	Take a picture when you Lock Out the equipment : 
				Take a picture when you Unlock the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
#1823 Baler06 Type: Reactive High DJ HEGARTY MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 06/27/2024	Total Time 12h 15m 9s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#2087 Baler06 codes Type: Reactive High DJ HEGARTY	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 08/02/2024	Total Time 10m 13s	Take a picture when you Lock Out the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
				Take a picture when you Unlock the equipment : 
#2114 BALER06 - 500 HOUR EQUIPMENT INSPECTION Type: Reactive Medium PREVENTIVE T PREVENTATIVE MAINTANCE DJ HEGARTY MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 08/10/2024	Total Part Costs\$290.04 Total Time1h 37m 10s Total Costs\$290.04	Take a picture when you Lock Out the equipment : 
				Take a picture when you Unlock the equipment :  BALER06 - HOURS METER

WORK ORDER INFO

LOCATION & ASSET

DUE & STATUS

TIME & COST

PROCEDURE ANSWERS

#2141

**BALER06 - 500 HOUR
EQUIPMENT
INSPECTION**

Type: Reactive

Medium

PREVENTIVE

T PREVENTATIVE
MAINTANCE

MARK MCCALVEY

DJ HEGARTY

MATTHEW COOK


EVERETT

BALER06 SIERRA

✓ Done

Completed by MARK
MCCALVEY on 08/12/2024BALER06 SIERRA:
BALER06 - HOURS METER: 5791 HOURS

Take a picture when you Lock Out the equipment :



Take a picture when you Unlock the equipment :



#2127

**Parts Request WO
#2123**

Type: Reactive

High

EVERETT

BALER06 SIERRA

✓ Done

Completed by JOHN GRACE
on 08/15/2024

PO Number: 1,071

Vendor Name: CUMMINS

Order Date: 08/07/2024

Due Date : 08/15/2024

WORK ORDER INFO

LOCATION & ASSET

DUE & STATUS

TIME & COST

PROCEDURE ANSWERS

T PARTS REQUEST


MARK MCCALVEY

JOHN GRACE

Pick up or Delivery:

☒ **Delivery**

A Picture of the Completed Order :



Received and Fulfilled Order:

Handwritten signature of John Grace.

#2123

Baler06

Type: Reactive

High

SAMANTHA
FORRINGER

MATTHEW COOK

EVERETT

BALER06 SIERRA

✓ Done


Completed by SAMANTHA
FORRINGER on 09/03/2024

Total Part Costs


\$212.48


Total Costs**\$212.48**

Take a picture when you Lock Out the equipment :




Take a picture when you Unlock the equipment :



WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
#2314 06 Baler Sierra Type: Reactive Medium MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 09/23/2024		Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#2545 Sierra 06 Type: Reactive Medium DJ HEGARTY MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 10/04/2024	Total Time 17h 32m 12s	Take a picture when you Lock Out the equipment :   Take a picture when you Unlock the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST		PROCEDURE ANSWERS
#872 BALER06 - REPLACE HYDRAULIC FILTERS - PM Type: Preventive T PREVENTATIVE MAINTANCE SAMANTHA FORRINGER DJ HEGARTY	EVERETT BALER06 SIERRA	03/06/2025 ✓ Done Completed by SAMANTHA FORRINGER on 10/08/2024	Total Part Costs Total Costs	\$1,169.94 \$1,169.94	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#2809 BALER06 - 500 HOUR EQUIPMENT INSPECTION Type: Reactive Medium PREVENTIVE T PREVENTATIVE MAINTANCE MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 11/11/2024	Total Part Costs Total Time Total Costs	\$84.36 1h 5m 15s \$84.36	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
				BALER06 - HOURS METER BALER06 SIERRA: BALER06 - HOURS METER: 9402 HOURS
#2876 BALER06 - 500 HOUR EQUIPMENT INSPECTION Type: Reactive Medium PREVENTIVE	EVERETT BALER06 SIERRA	⊖ Canceled Canceled by SAMANTHA FORRINGER on 11/12/2024		
#2881 Parts Request WO #2880 Type: Reactive High T PARTS REQUEST MATT CHUM	EVERETT BALER06 SIERRA	✓ Done Completed by MATT CHUM on 12/02/2024		PO Number: 1,803 Vendor Name: sierra baler Order Date: 11/22/2024 Due Date : 11/26/2024 Pick up or Delivery: ☒ Delivery A Picture of the Completed Order :  Received and Fulfilled Order: 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
#2880 BALER06 Sierra Type: Reactive Medium MARK MCCALVEY DJ HEGARTY MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MARK MCCALVEY on 12/03/2024	Total Time 113h 48m 53s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 
#3134 BALER06 Sierra Type: Reactive Medium DJ HEGARTY MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by DJ HEGARTY on 12/18/2024	Total Time 265h 48m 50s	Take a picture when you Lock Out the equipment : 

WORK ORDER INFO	LOCATION & ASSET	DUE & STATUS	TIME & COST	PROCEDURE ANSWERS
				Take a picture when you Unlock the equipment : 
#3225 Sierra Hose Type: Reactive Medium MATTHEW COOK	EVERETT BALER06 SIERRA	✓ Done Completed by MATTHEW COOK on 12/24/2024	Total Time 14m 8s	Take a picture when you Lock Out the equipment :  Take a picture when you Unlock the equipment : 

Signed off by

Date