

Service Report



15075 Aljon Avenue
Ottumwa, Iowa 52501
1-800-255-6620
www.aljon.com

Company:	
Street:	
City:	
Phone:	
Yard Manager:	

	Hour	Rate
Labor	6	\$175.00
TRAVEL	1	1950.00
Overnight	2	\$250.00

Machine Type Baler	Model 580CL	Hours unknown	Warranty ____ No Warranty X
S/N 14563	Customer PO# n/a		

Service Requested. Overall Condition.

Customer requested inspection for rebuild. Job 25909. The overall condition of the machine is poor. All electrical harnesses, and multiple electric components need to be replaced. The hydraulic hoses show signs of heavy wear. Multiple hoses are blistered or chaffed. The machine could not be operated due to missing batteries and multiple harnesses problems.

Observations

Trailer: Fair Condition. Has a few cracked welds. The 580CL serial number and VIN plate is missing.
Engine: Condition unknown. Engine will not run.
Hydraulics: The overall condition is poor. It is recommended that all hydraulic hoses be replaced. The machine is missing one lid cylinder. The hydraulic reservoir did not have a cap on it. It is highly plausible that the hydraulic oil is contaminated and the reservoir full of water. Because the unit is currently not operational, the overall condition of the hydraulic components is unknown. Multiple clamps are missing or damaged.
Material Handler: Condition unknown. The machine could not be operated to test functionality.
Electrical: The overall condition is poor. All engine and baling function electrical components will need to be replaced.

Service Report

Overall Recommendation for Rebuild:
--

1. Replace all baling function electrical harnesses and components.
2. Clean hydraulic reservoir and fill it with clean hydraulic oil.
3. Fix or replace all missing clamps.
4. Install missing 8 X 29 Lid Cylinder and adapters.
5. Clean the machine so that a better visual inspection can be performed.
6. Operate the machine to determine if other repairs are necessary.

Please consider that the electrical harnesses and hydraulic manifold assembly are obsolete on this machine. Parts may or may not be available at the time of purchase. Lead times for electrical harnesses can be up to 16 weeks.

C&C Manufacturing is estimating the cost of repair only and is not committed to repairing the machine. Local service contractor rates may vary.

	Parts Quote 16883 Total:	\$28,237.08
	Labor Estimate	100 hours @ 175.00 = \$17,500 (Does not include travel, hotel or per diem)
	Freight Estimate	\$1,000.00
	Misc Material	\$500.00
	Customer Repair Estimate	\$42, 237.08

Serviced By: Chris Hepler

Approved By: Jason Mills